



A new torque tester is born

Torque tester **NDI-800CN** **NDI-80CN**

- **Measure the time.**

Date and time and other information are allocated to memory data. When something goes wrong, you can quickly check past data.

- **Look at pass / fail.**

Tilt color liquid crystal is used for the display board. Pass / fail result and various information are displayed in an easy-to-understand manner.

- **Operate with a PC.**

By connecting with the personal computer, all the control of the main body can be done with the personal computer. Easy setting of numerical values and data can be done easily.

- **Connect with PLC.**

RS232C output is also equipped as standard. Since I / F specification of communication is also disclosed, you can control exactly from PLC as you wish.

- **Work with dry batteries**

Either external power source or dry battery can be used. Lifetime replacement of troublesome rechargeable batteries is unnecessary.

Show the tester specification below.

Model	NDI-80CN	NDI-800CN															
Range	0.020 ~ 8.160 kgf·cm	0.20 ~ 81.60 kgf·cm															
	0.018 ~ 7.080 lbf·in	0.18 ~ 70.80 lbf·in															
	2.0 ~ 800.0 mN·m	0.020 ~ 8.000 N·m															
Unit	kgf·cm / lbf·in / mN·m	kgf·cm / lbf·in / N·m															
Accuracy	±0.5% (If the value is 499 digit or less, the accuracy ±3 digit.)	±0.5% (If the value is 499 digit or less, the accuracy ±3 digit.)															
Sampling rate	1000 data / 1 second																
Measurement mode	<table border="1"> <thead> <tr> <th colspan="2">Symbol</th> <th>Contents</th> </tr> </thead> <tbody> <tr> <td>Peak hold</td> <td>PP</td> <td>Hold the inputted maximum value.</td> </tr> <tr> <td>Peak down</td> <td>PD</td> <td>Hold the inputted first peak value.</td> </tr> <tr> <td>Real time output</td> <td>C</td> <td>Use at the measurement of torque wave. Sampling rate is 250 data / 1 second.</td> </tr> <tr> <td>Track</td> <td>TR</td> <td>Use at the calibration mainly. Display the load torque value.</td> </tr> </tbody> </table>		Symbol		Contents	Peak hold	PP	Hold the inputted maximum value.	Peak down	PD	Hold the inputted first peak value.	Real time output	C	Use at the measurement of torque wave. Sampling rate is 250 data / 1 second.	Track	TR	Use at the calibration mainly. Display the load torque value.
	Symbol		Contents														
	Peak hold	PP	Hold the inputted maximum value.														
	Peak down	PD	Hold the inputted first peak value.														
	Real time output	C	Use at the measurement of torque wave. Sampling rate is 250 data / 1 second.														
Track	TR	Use at the calibration mainly. Display the load torque value.															
Memory capacity	400 data																
Clock	Store the measurement date.																
Power	AC adaptor (12V) / AA battery																
Socket size	□20 / □9.5																
Accessories (one pieces each)	(measurement joint) OW-025 / OW-10	(measurement joint) OW-20 / OW-60															
	Cube with screw holes of M2.6, M3, M4, M5 and M6 (size 20×20×20mm)																
	AC adaptor (input : AC100~240V (50/60Hz), output : DC12V)																
	USB cable (mini B type)																
	AA size cell×4																
	Result of calibration, Certification on calibration, Traceability system figure																



WARNING. Don't use for the measurement of impact tools

Detailed contents are animated <https://youtu.be/gv7ErjlfyT8>

