Surface Resistance Meter



RoHS Compliant

Description

This meter has been designed to measure both surface resistance and resistance to ground. To measure surface material place the meter on the area to be tested and press the test button. For measuring resistance to ground, place the ground lead into the earth leakage socket, connect the crocodile clip to the area to be tested and press the test button.

The meter will test conductive, static dissipative and insulative surfaces using two parallel bars set to give Ohms per square readings. Conductive is indicated by green LEDs from 10^3-10^5 , static dissipative by yellow LEDs from 10^6-10^{11} and insulative by red LEDs $10^{12}+$.



Technical Data

Technical Specification	Techn	Technical Data	
Decade Changeover	+/- 1/2 Decade on a Log	+/- 1/2 Decade on a Logarithmic Scale (3.16 x 10n)	
Resolution	1 Decade		
Accuracy	+/- 1/2 Decade		
Temperature	Operating	5°C to 49°C	
	Storage	-15°C to +60°C	
Power	9V PP3 AI	9V PP3 Alkaline Battery	
Test Voltage	Non	Nominal 9V	
Accuracy	+/-	+/- 10%	
Repeatability	+,	+/- 5%	
Weight	6.0	6 Ounces	

Operation

Remove battery panel and insert PP3 Alkaline battery. To check the battery, hold down the unit in the air and press the test button, the red LED should show (insulative). Place the meter onto the surface, ensuring the probes are touching the area to be tested and press the test button. The LED that is illuminated shows the relevant results in Ohms per square.

Checking Resistance to Ground

Insert the grounding lead into the earth leakage socket and connect the crocodile clip to the ground connection. Place the meter onto the surface being tested, and hold down the test button. The measurement will show the resistance to ground in Ohms rather than Ohms per square.

Newark.com/multicomp-pro Farnell.com/multicomp-pro Element14.com/multicomp-pro



Page <1> 11/11/20 V1.0

Surface Resistance Meter



RoHS Compliant

Notes

Calibration should be carried out annually (please contact us for more information). The meter comes complete with ground lead. Battery not supplied.

Part Number Table

Part Number	Description	
MP005768	Surface Resistance Meter	