



Very reliable due to minimal dependency on temperature

Indicator  
- green for dry  
- yellow for wet

Designed for CFC and HCFC

Tightening gasket

Connections:  
solder x solder (illustrated),  
flare ext. x ext. or  
flare int. x ext.

Max. working pressure:  
35 bar

Working temperature range:  
-50 to 80°C

