



# LOCTITE<sup>®</sup> Copper Hi-Temp Gasket Sealant Spray

January 2007

## PRODUCT DESCRIPTION

LOCTITE<sup>®</sup> Copper Hi-Temp Gasket Sealant Spray provides the following product characteristics:

<b>Technology</b>	Phenolic Copper Based
Chemical Type	Phenolic
Appearance	Gold mist <sup>LMS</sup>
<b>Cure</b>	Air dry
<b>Application</b>	Sealing
Specific Benefit	<ul style="list-style-type: none"> <li>Remains tacky indefinitely</li> <li>Fills surface imperfections</li> <li>Resists shop fluids, including gasoline</li> </ul>

LOCTITE<sup>®</sup> Copper Hi-Temp Gasket Sealant Spray is an aerosol product formulated as an adhesive/sealant which helps dissipate heat and prevents gasket burnout. Typical applications include cylinder head gaskets, exhaust manifold gaskets, turbo charger flanges, and carburetor gaskets. LOCTITE<sup>®</sup> Copper Hi-Temp Gasket Sealant Spray contains metallic copper to improve heat transfer and eliminate hot spots. This product is typically used in applications with an operating range of -50 °C to +500 °C.

## TYPICAL PROPERTIES

Specific Gravity @ 25 °C	0.8
Flash Point - See MSDS	
Viscosity @ 22 °C, mPa·s (cP)	
Solids/Non-Volatile Content, %	14.1 to 16.1 <sup>LMS</sup>

## GENERAL INFORMATION

**This product is not recommended for use in pure oxygen and/or oxygen rich systems and should not be selected as a sealant for chlorine or other strong oxidizing materials.**

**For safe handling information on this product, consult the Material Safety Data Sheet (MSDS).**

## Directions for use

- Provide adequate ventilation.
- Ensure all surfaces are free of any dirt and oil.
- Mask areas that should not be coated.
- Shake can with ball agitator thoroughly for 1 minute before use.
- Best results are obtained when the product is at room temperature.
- Spray an even coat of LOCTITE<sup>®</sup> Copper Hi-Temp Gasket Sealant Spray from a distance of about 20 to 25 cm onto the flange surface and on both sides of the gasket.
- Avoid overspray.

- Allow LOCTITE<sup>®</sup> Copper Hi-Temp Gasket Sealant Spray to fully evaporate from parts prior to bonding to avoid solvent entrapment within the bond joint.
- NOTE:** Aerosol product will coat 10 to 12 standard gaskets.

## Clean-up

- Turn can upside-down and spray to clear nozzle.
- Clean hands with hand cleaners.

## Loctite Material Specification<sup>LMS</sup>

LMS dated January 16, 2002. Test reports for each batch are available for the indicated properties. LMS test reports include selected QC test parameters considered appropriate to specifications for customer use. Additionally, comprehensive controls are in place to assure product quality and consistency. Special customer specification requirements may be coordinated through Henkel Quality.

## Storage

The product is classified as flammable and must be stored in an appropriate manner in compliance with relevant regulations. Do not store near oxidizing agents or combustible materials. Store product in the unopened container in a dry location. Storage information may also be indicated on the product container labelling.

**Optimal Storage: 8 °C to 21 °C. Storage below 8 °C or greater than 28 °C can adversely affect product properties.** Material removed from containers may be contaminated during use. Do not return product to the original container. Henkel cannot assume responsibility for product which has been contaminated or stored under conditions other than those previously indicated. If additional information is required, please contact your local Technical Service Center or Customer Service Representative.

## Conversions

(°C x 1.8) + 32 = °F
kV/mm x 25.4 = V/mil
mm / 25.4 = inches
µm / 25.4 = mil
N x 0.225 = lb
N/mm x 5.71 = lb/in
N/mm <sup>2</sup> x 145 = psi
MPa x 145 = psi
N·m x 8.851 = lb·in
N·m x 0.738 = lb·ft
N·mm x 0.142 = oz·in
mPa·s = cP

**Note**

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, **Henkel Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Henkel Corporation's products. Henkel Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits.** The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Henkel Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more United States or foreign patents or patent applications.

**Trademark usage**

Except as otherwise noted, all trademarks in this document are trademarks of Henkel Corporation in the U.S. and elsewhere. ® denotes a trademark registered in the U.S. Patent and Trademark Office.

Reference 0.0