

Measuring Tool

55190 ZIP50 Z-Axis Presetter (Indicator Type)



Features :

- ▶ Setting tool length on CNC milling and lathe machines
- ▶ Setting height: $50 \pm 0.005\text{mm}$.
- ▶ Large measuring surface and easily operated.
- ▶ Low spring force to avoid breakage of small end mill or drill.
- ▶ Easily calibrated by ground parallel or gauge blocks.

55200 ZIP50A Z-Axis Presetter (Indicator Type)



Features :

- ▶ Setting tool length on CNC milling and lathe machines
- ▶ Setting height: $50 \pm 0.005\text{mm}$.
- ▶ Large measuring surface and easily operated.
- ▶ Low spring force to avoid breakage of small end mill or drill.
- ▶ Easily calibrated by ground parallel or gauge blocks.
- ▶ ZIP-50A with better parallel, sensibility and accuracy.

MEASURING TOOL

Unit:mm

Order No.	Model	Height	G.W.	LxWxH	N.W.
55190	ZIP50	50 ± 0.005	1.2kgs	101x101x90	0.59kgs
55200	ZIP50A	50 ± 0.005	1.8kgs	101x101x90	1.06kgs