


# G-D2 Wiring Diagram



## Warning!

**DO NOT** connect 230v AC mains directly to the G-D2 board! It must be connected through a stepdown transformer with output of 13v AC.