## TPI 368 NON-CONTACT CLOSE-FOCUS INFRARED THERMOMETER W/O LASER (-22° to 120°C)

+/- Calculation

+/- 2% Or +/- 2°C Whichever Is Greater

Example: +/- 2%

A) Detected 35°C (It can be 35°C as well) + 2% = 35.7°C - 2% = 34.3°C

Example: +/- 2°C

B) Detected 35°C (It can be 35°C as well)

 $+ 2^{\circ}C = 37^{\circ}C$   $- 2^{\circ}C = 33^{\circ}C$