Cleaning Hood Folding Instructions



1. Fold the 1 # Edge into 90 degrees



2.Fold the 3 # Edge into 90 degrees




3. Fold both sides of 2 and 4 in half at the same time



4. Fold both risers in the middle



5. Fold the riser so that it is parallel to the two pipes below



6. Fold the bottom two tubes in half. Folding is complete.