

Precision Machinery

69410 GAQ Air Tapping Machine



Features:

- ▶ High tapping efficiency and no easy to break tap.
- ▶ Adopting pneumatic and suitable for Steel, Iron, Copper, Plastic materials tapping.
- ▶ Universal arm design for lateral, vertical, any angle tapping.
- ▶ Work table is not included, optional accessory.

Standard Accessories:

1. Air Tapping Spindle
2. Extended Arm
3. Fixed Base
4. 3-points Combination
5. Safety Torque Tapping Collets x 6 pcs
6. Swing Arm

| Order No. | Model | Capability | Spindle Speed R.P.M. | Work Range | N.W. |
|-----------|-------|------------|----------------------|--------------------------|-------|
| 69410-01 | GAQ08 | M2-M8 | 700 | Rmax 950mm Rmin 100mm | 20 kg |
| 69410-02 | GAQ12 | M3-M12 | 400 | | 25kg |
| 69410-03 | GAQ16 | M3-M16 | 300 | | 25kg |

Unit:mm

69420 GAQ Air Tapping Machine



Features:

- ▶ High tapping efficiency and no easy to break tap.
- ▶ Adopting pneumatic and suitable for Steel, Iron, Copper, Plastic materials tapping.
- ▶ Universal arm design for lateral, vertical, any angle tapping.
- ▶ Work table is not included, optional accessory.

Standard Accessories:

1. Air Tapping Spindle
2. Extended Arm
3. Fixed Base
4. 3-points Combination
5. Safety Torque Tapping Collets x 6 pcs
6. Swing Arm

| Order No. | Model | Capability | Spindle Speed R.P.M. | Work Range | N.W. |
|-----------|-------|------------|----------------------|---------------------------|------|
| 69420-01 | GAQ20 | M3-M20 | 150/400 | Rmax 1000mm Rmin 100mm | 25kg |
| 69420-02 | GAQ22 | M3-M22 | 120/300 | | 25kg |
| 69420-03 | GAQ24 | M3-M24 | 100/300 | | 25kg |
| 69420-04 | GAQ30 | M3-M30 | 40/200 | | 25kg |

Unit:mm