

Handing Procedure

1 Weighing

Liquid&Powder Mix Ratio: Fast Heat Curing: 1ml:2.4g

Traditional Heat Curing: 1ml:2.34g

Self Curing: 1ml:2.2g



4 Adjusting

Tight the flask by Hydraulic Press Machine.



2 Kneading&Mixing


Put the Liquid and Powder in the kneading bag, seal it immediately, and mix them evenly with hands. Then leave the mixture under room temperature 23 °C for 15 minutes until it becomes dough.



5 Curing


Fast Heat Curing: Put into 100 °C water, keep boiling for 20mins, and then cool down naturally.

Traditional Heat Curing: Put into cold water, boil the water to 100 °C in 30mins, keep boiling for 60mins and then cool down naturally.



20mins Bench Cool

Self Curing: Can be cured at normal temperature. After the initial curing we suggest putting the flask into 60 °C hot water for 30mins to cure completely and then cool down naturally.



3 Working

Take the mixture out and fill the flask. Maximum working time is 10 minutes.



Shade

- 5 Shades: 2S,2ST,3ST, I, V
- Popular Shades: 2S, 2ST,3ST





Storage

- Store in a ventilated place, and be protected from naked fire, high temperature and direct sunshine;
- Validity: Powder 3 years, Liquid 2 years