



APPLICATION REPORT

Application Reports are an excellent way to share knowledge throughout the Blagdon sales network. Reports will be available to all unless stated. If any part of this report should remain confidential and not published, please highlight or inform Joanne Shutt



PUMP MODEL

B4002AABBTTA (Aluminium / PTFE)

INDUSTRY

Industrial Paint

DESCRIPTION OF PROCESS/APPLICATION

Industrial paint mixing. This 1.5" pump was trolley mounted for moving around the facility, pumping at multi-station paint transfers.

Previous pumps were supplied by a competitor – the customer had repeated failures with both valve and diaphragm failures. When the diaphragms, supplied by the competitor failed, it was technically very difficult to replace all damaged air side parts and also very expensive.

The customer changed to Blagdon and is very happy with the quality, product simplicity and the low cost of ownership compared to previous manufacturers. The pump has been in service for 14 years.

PUMP STATISTICS

DUTY	Industrial Paint	FLOWRATE	N/A
HEAD	N/A	AIR PRESSURE	3 bar

ANY OTHER INFORMATION

Flooded suction.

BLAGDON PUMP HOLDINGS LIMITED

Lambert Road, Armstrong, Washington, Tyne & Wear, NE37 1QP. U.K.
 Tel: +44 (0) 191 417 7475 Fax: +44 (0) 191 417 5435
 Email: sales@blagdonpump.com Website: www.blagdonpump.com