SIALE TITE

Success Story



McDonald's® Restaurant

With a hardness level of 27 grains, this **McDonald's**[®] experienced all the problems associated with hard waterscale buildup in faucets, toilets and sinks, a dishwasher constantly clogged up and other problems.

McDonald's® Restaurant State College, PA

A Solution...

They were approached by a **ClearWater** dealer who offered a solution to their problems - the **ScaleBlaster**TM. The concept of a low cost device that required no chemicals, salts or maintenance was intriguing to the owners.



ClearWater Enviro Tech's electronic descaler, the ScaleBlaster™.



ScaleBlaster[™] installed at the McDonald's[®] location pictured above.

Fantastic!

On September 26, 1997, the ScaleBlasterTM unit was installed. Within days, employees noticed a difference in the water. The scale buildup in the faucets had disappeared, the toilets were easier to clean, and the overhead sprayer on the dishwasher was no longer clogging up. Calcium spotting had diminished. Everything seemed fine and dandy until the ClearWater dealer showed up for a follow-up call on November 20, 1997.

OOPS!

"Your unit was working just fine--doing everything you said it would, but up until two weeks ago, our hard water problems came back again" was the report given to him from **McDonald's** management.

Upon inspection, the **ClearWater** dealer found scale had indeed returned again. Astonished, he asked the manager if he could go back and visually inspect the unit. What he found upset him. The unit was unplugged and hanging off the wall. Apparently two weeks ago, some remodeling was done in the room and the unit was left hanging in the middle of nowhere and never reconnected.



This is how a plumbing company left **ScaleBlaster**[™] after some remodeling was done near the unit. The scaling problems resumed within days, frustrating the cleaning crew who had become accustomed to the easier way it was to clean up.

Back to Normal

The dealer hooked the unit up again at no charge, and once again the unit went back to work and within days, everything was descaling again. Even the cleaning crew, who had no idea the unit was even installed, were commenting how easy it was to clean again.

 \Rightarrow

401 Mountain Ros Pennsylvania 16801 814/466-7400 Fax: 814/466-6934



DATE December 8, 1997 ClearWater Enviro Technologies Clear water Envito 1601 1054 Kapp Drive Clearwater, FL 34625

Just a short note to inform you of an experience we had with one of your Scale Blaster units at one of our McDonalds restaurants. Just a snort note to intorm you or an experi-units at one of our McDonalds restaurants.

After the initial installation in late September, 1997, the write calcium bullar on that it up until bathrooms and kitchen due to the excessively two months later, one of your representative bathrooms and kitchen due to the excessively two months and utry reported that "up unif bathrooms and kitchen due to the excessively two months and utry reported that "up unif bathrooms and kitchen disappeared. About two had again." Workers doing the bathrooms and repair disappeared the manager then on dutry reported to the bathrooms and repair of check was great! On that construction workers doing the maintenance of follow-up water was great found that construction and pulled in stopped by for a follow-up water (it was disconnected the unit and connected by to be stopped by for a follow-up water furty of the was disconnected the unit and connected specially on the considerable form and septimentally at no charge reinstallation by your representative was calciumly at no charge the expect the case of soap aintenance and repair wall. It was immediately had been great ever unit in terms of soap aintenance and representative. The walling the Scale Blaster unit in and fixture maintenance and representative.

The provided in the calcium of the calcium of the considerable from installing the specially plumbing and fixture maintenance supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time supplies and time and effort and especially plumbing and time and effort and experience and the write and the write and the provided that the unit and c considerable from installing the Scale Blaster unit in terms of soap usage, cleaning and repairl and especially plumbing and fixture maintenance and repairl supplies and time and effort and especially plumbing and fixture maintenance and repairl We enclosed some pictures of the initial installation and the way it was found by your lime scale product and recommend we love the product and recommend was enclosed some pictures of the initial installation was found by your w

Sincerely.

McDonald's is a registered trademark of McDonald's Corporation



Letter written by Bruce Rittenhouse part owner of 6

franchises, confirms our amazing story

McDonald's

about the

ScaleBlasterTM.

A Revolution in Water Purification Clearwater, Florida







World-Wide Distribution in over 75 countries

Clearwater-Enviro.com

© 2007 Clearwater Envrio Technologies, Inc.

Corporate Office

1166 Kapp Drive Clearwater, FL 33765

Toll Free 1.800.756.7946 Phone 727,562,5186 Fax 727,562,5187